

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 05/13/2011

FORM APPROVED

OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155231		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 04/25/2011	
NAME OF PROVIDER OR SUPPLIER RANDOLPH NURSING HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 701 S OAK STREET WINCHESTER, IN47394			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0000	<p>A Life Safety Code Recertification and State Licensure Survey was conducted by the Indiana State Department of Health in accordance with 42 CFR 483.70(a).</p> <p>Survey Date: 04/25/11</p> <p>Facility Number: 000136 Provider Number: 155231 AIM Number: 100275450</p> <p>Surveyor: Mark Bugni, Life Safety Code Specialist</p> <p>At this Life Safety Code survey, Randolph Nursing Home was found not in compliance with Requirements for Participation in Medicare/Medicaid, 42 CFR Subpart 483.70(a), Life Safety from Fire and the 2000 edition of the National Fire Protection Association (NFPA) 101, Life Safety Code (LSC), Chapter 19, Existing Health Care Occupancies and 410 IAC 16.2.</p> <p>This one story facility was determined to be of Type V (111) construction and fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors and spaces open to the corridors. The facility has a capacity of 88 and had a census of 74 at the time of this visit.</p>			K0000			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (see instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155231		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 04/25/2011	
NAME OF PROVIDER OR SUPPLIER RANDOLPH NURSING HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 701 S OAK STREET WINCHESTER, IN47394			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0027 SS=E	<p>Quality Review by Robert Booher, REHS, Life Safety Code Specialist-Medical Surveyor on 04/27/11.</p> <p>The facility was found not in compliance with the aforementioned regulatory requirements as evidenced by the following</p> <p>Door openings in smoke barriers have at least a 20-minute fire protection rating or are at least 1¾-inch thick solid bonded wood core. Non-rated protective plates that do not exceed 48 inches from the bottom of the door are permitted. Horizontal sliding doors comply with 7.2.1.14. Doors are self-closing or automatic closing in accordance with 19.2.2.2.6. Swinging doors are not required to swing with egress and positive latching is not required. 19.3.7.5, 19.3.7.6, 19.3.7.7 Based on observation and interview, the facility failed to ensure 1 of 6 sets of smoke barrier doors would restrict the movement of smoke for at least 20 minutes. LSC 19.3.7.6 requires doors in smoke barriers shall comply with Section 8.3.4. 8.3.4.1 requires doors in smoke barriers shall close the opening leaving only the minimum clearance necessary for proper operation which is defined as 1/8 inch. This deficient practice could affect 14 residents who reside on the 300 Hall.</p> <p>Findings include:</p>			K0027	<p>K027</p> <p>Please accept this plan of correction as our credible allegation of compliance with all regulatory requirements</p> <p><u>Corrective action for affected resident</u></p> <p>It is the intent of this facility to ensure swinging doors are arranged so that each door shall be self-closing and latch. The 300 wing set of doors were repaired on April 25, 2011 to close and latch as required.</p> <p><u>Identification of other residents at</u></p>		05/11/2011

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155231		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		X3) DATE SURVEY COMPLETED 04/25/2011	
NAME OF PROVIDER OR SUPPLIER RANDOLPH NURSING HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 701 S OAK STREET WINCHESTER, IN47394			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0046 SS=E	Based on observation on 04/25/11 at 10:45 a.m. with the maintenance supervisor, the 300 Hall set of smoke barrier doors next to the therapy room had a two foot gap where the south door in the set dragged on the floor on two separate attempts to close the smoke barrier doors. This was verified by the maintenance supervisor at the time of observation. 3.1-19(b)			K0046	<u>risk:</u> All setts oft ftre doors have been ttested tto ensure tthatt each door closes and lattches as required <u>Measures tto ensure tthis deftcientt practice does nott recur</u> Maintenance sttaft has been re-educattted tto ftederal regulatton K27. All ftre doors will be placed on a preventtve mainttenance program ensuring all ftre doors close and lattch as required (see form Attachmentt A) <u>Monittoring oft correcttve acttqn</u> All ftre doors will be placed on a preventtve mainttenance program ensuring all ftre doors close and lattch as required(see form Attachmentt A. The maintenance supervisor or his designee will review each smoke barrier door using form Attachmentt A as partt oft Randolph's Quality Assurance Program, ensuring tthe LSC requiremттt tthatt each door closes and lattches as required		05/11/2011
	Emergency lighting of at least 1½ hour duration is provided in accordance with 7.9. 19.2.9.1. Based on record review and interview, the facility failed to ensure 1 of 1 battery backup lights was tested at 30 day intervals and annually for a 90 minute duration to ensure the light would provide lighting during periods of power outages				K046 Please accepti tthis plan of correction as our credible allegation of compliance with all regulatory requirements <u>Correcttve acttqn ffor affectted residentt</u>		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155231		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 04/25/2011	
NAME OF PROVIDER OR SUPPLIER RANDOLPH NURSING HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 701 S OAK STREET WINCHESTER, IN47394			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	<p>to protect any resident using the main dining room. LSC 19.2.9.1 requires emergency lighting shall be provided in accordance with Section 7.9. Section 7.9.3 requires a functional test shall be conducted on every required emergency lighting system at 30-day intervals for not less than 30 seconds. Equipment shall be fully operational for the duration of the test. Written records of visual inspections and tests shall be kept by the owner for inspection by the authority having jurisdiction. This deficient practice could affect any residents who use the main dining room.</p> <p>Findings include:</p> <p>Based on an interview on 04/25/11 at 9:40 a.m. with the maintenance supervisor, the facility has one battery backup light located in the main dining room. Based on a review of the Preventive Maintenance Log Book and the Fire Drill Log book, there was no evidence the battery powered backup light was tested at thirty day intervals for 30 seconds, or annually for a ninety minute duration. This was verified by the maintenance supervisor at the time of record review.</p> <p>3.1-19(b)</p>				<p>Itt Is the inttentt oft tthis ftacilityt to provide emergency lighttng oft att leastt1 ½ hr duratton. The battery back up lightt locatted in tthe Main Dining Room has been removed. Lighttng in tthe Main Dining room had been added tto tthe generattor battery back up lightt is nott needed</p> <p>- <u>Identtftcatton oft otther residentts att risk;</u></p> <p>Itt Is the inttentt oft tthis ftacilityt to provide emergency lighttng oft att leastt1 ½ hr duratton. The battery back up lightt locatted in tthe Main Dining Room has been removed. Lighttng in tthe Main Dining room had been added tto tthe generattor battery back up lightt is nott needed</p> <p>- <u>Measures to ensure tthis deftcientt practce does nott recur</u></p> <p>Itt Is the inttentt oft tthis ftacilityt to provide emergency lighttng oft att leastt1 ½ hr duratton. The battery back up lightt locatted in tthe Main Dining Room has been removed. Lighttng in tthe Main Dining room had been added tto tthe generattor battery back up lightt is nott needed</p> <p>- <u>Monittoring oft correcttve acttgn</u></p> <p>Itt Is the inttentt oft tthis ftacilityt to provide emergency lighttng oft att leastt1 ½ hr duratton. The battery back up lightt locatted in tthe Main Dining Room has been removed. Lighttng in tthe Main Dining room had been added tto tthe generattor</p>		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155231		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 04/25/2011	
NAME OF PROVIDER OR SUPPLIER RANDOLPH NURSING HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 701 S OAK STREET WINCHESTER, IN47394			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0047 SS=E	<p>Exit and directional signs are displayed in accordance with section 7.10 with continuous illumination also served by the emergency lighting system. 19.2.10.1</p> <p>Based on observation and interview, the facility failed to ensure 1 of 12 illuminated exit and directional signs was provided with continuous illumination. This deficient practice could affect 14 residents who reside on the 300 Hall near the therapy room.</p> <p>Findings include:</p> <p>Based on observation on 04/25/11 at 10:35 a.m. with the maintenance supervisor, the 300 Hall exit and directional sign above the exit door across from the therapy room was not illuminated. Based on an interview with the maintenance supervisor on 04/25/11 at 10:40 a.m., the exit and directional sign has a burned out light bulb.</p> <p>3.1-19(b)</p>			K0047	<p>battery back up lightt is nott needed</p> <p>K047</p> <p>Please accepti this plan of correction as our credible allegation of compliance with all regulatory requirementis</p> <p>-</p> <p><u>Correcttve actton ftor affectted residentt</u></p> <p>Itt is tthe inttentt oft tthis ftacilityt to ensure all exitt and directtonal signs are displayed witht contnuous illuminatton. On April 25, 2011, tthe lightt bulb to tthe exitt sign locatted on tthe 300hall was replaced, tthe exitt sign proved tto be in working order providing illuminatton.</p> <p><u>Identtftcatton oft otther residentts att risk;</u></p> <p>All settt oft exitt and directtonal signs were reviewed and proved tto be in working order.</p> <p><u>Measures to ensure tthis deftcientt practtce does nott recur</u></p> <p>Mainttenance sttaft has been re-educattt to ftederal regulatton K47. All exitt and directtonal signs will be placed on a preventtve mainttenance program ensuring exitt and directtonal signs have contnuous illuminatton</p> <p>-</p> <p><u>Monittoring oft correcttve acttton</u></p> <p>All exitt and directtonal signs will be</p>		05/11/2011

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155231		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 04/25/2011	
NAME OF PROVIDER OR SUPPLIER RANDOLPH NURSING HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 701 S OAK STREET WINCHESTER, IN47394			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
K0050 SS=F	<p>Fire drills are held at unexpected times under varying conditions, at least quarterly on each shift. The staff is familiar with procedures and is aware that drills are part of established routine. Responsibility for planning and conducting drills is assigned only to competent persons who are qualified to exercise leadership. Where drills are conducted between 9 PM and 6 AM a coded announcement may be used instead of audible alarms. 19.7.1.2</p> <p>Based on record review and interview, the facility failed to conduct quarterly fire drills on each shift for 3 of 4 quarters during the past year to protect 74 of 74 residents. This deficient practice affects all residents in the facility.</p> <p>Findings include:</p> <p>Based on a review of the Fire Drill Log book with the maintenance supervisor on 04/25/11 at 9:00 a.m., there was no record of a fire drill conducted for the third shift, first quarter of the year 2011; second or</p>			K0050	<p>placed on a preventive maintenance program ensuring all exit and directional signs have continuous illumination (see form attachment B). The maintenance supervisor or his designee will review each exit and directional signs using (see form Attachment B) as part of Randolph's Quality Assurance Program ensuring the LSC requirement that each exit and directional signs have continuous illumination</p> <p>K50 <u>Corrective action for affected resident:</u> It is the intent of this facility to hold fire drills at unexpected times under varying conditions at least quarterly on each shift. A Fire Drill was conducted on April 13, 2011/first shift and May 10, 2011/third shift, Quarter II for the year 2011. <u>Identification of other residents at risk:</u> Maintenance staff has been re-educated to federal regulation K50. A Fire Drill was conducted on April 13, 2011/first shift and May 10, 2011/third shift, Quarter II for the year 2011. <u>Measures to ensure</u></p>		05/11/2011

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155231		X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		X3) DATE SURVEY COMPLETED 04/25/2011	
NAME OF PROVIDER OR SUPPLIER RANDOLPH NURSING HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 701 S OAK STREET WINCHESTER, IN47394			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE	
K0076 SS=E	third shift for the third quarter of the year 2010; and the first shift, second quarter of the year 2010. Based on an interview with the maintenance supervisor on 04/25/11 at 9:25 a.m., and after a fifteen minute review of the Fire Drill Log book, the maintenance supervisor indicated there was no other documentation available for review to verify a third shift fire drill for the first quarter of 2011, a second and third shift fire drill for the third quarter of 2010, and a first shift fire drill for the second quarter of 2010. 3.1-19(b)			<u>this deficient practice does not recur</u> ; Maintenance staff has been re-educated to federal regulation K50. A Fire Drill was conducted on April 13, 2011/first shift and May 10, 2011/third shift, Quarter II for the year 2011. <u>Monitoring of corrective action</u> ; Maintenance staff has been re-educated to federal regulation K50. A Fire Drill was conducted on April 13, 2011/first shift and May 10, 2011/third shift, Quarter II for the year 2011. Form (Attachment C) has been initiated to assist in conducting fire drills at unexpected times, under varying conditions, at least quarterly each shift. Form (Attachment C) will become part of Randolph's Quality Assurance Program, ensuring the LSC requirement of conducting fire drills at unexpected times, under varying conditions, at least quarterly each shift.			
	Medical gas storage and administration areas are protected in accordance with NFPA 99, Standards for Health Care Facilities. (a) Oxygen storage locations of greater than 3,000 cu.ft. are enclosed by a one-hour separation. (b) Locations for supply systems of greater than 3,000 cu.ft. are vented to the outside. NFPA 99 4.3.1.1.2, 19.3.2.4 Based on observation and interview, the facility failed to ensure a minimum distance of at least five feet separated combustible materials from oxygen		K0076	K076 <u>Corrective action for affected resident</u> It is the intent of this facility to maintain a minimum distance of		05/11/2011	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155231		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 04/25/2011	
NAME OF PROVIDER OR SUPPLIER RANDOLPH NURSING HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 701 S OAK STREET WINCHESTER, IN47394			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	<p>containers in 1 of 1 oxygen storage areas. NFPA 99, 8-3.1.11.2(c) requires oxidizing gases such as oxygen shall be separated from combustibles by a minimum distance of five feet if the required storage location is protected by an automatic sprinkler system. This deficient practice could affect 14 resident who reside on the 300 Hall near the oxygen storage room.</p> <p>Findings include:</p> <p>Based on observation on 04/25/11 at 11:15 a.m. with the maintenance supervisor, the 300 Hall oxygen storage room had three full liquid oxygen containers stored within one foot of eight shelves of combustible plastic oxygen supplies stored in cardboard boxes. This was verified by the maintenance supervisor at the time of observation.</p> <p>3.1-19(b)</p>				<p>between liquid oxygen and combustble matteral All combustble matteral has been removed ffrom tth@00 hall oxygen sttorage room</p> <p><u>Identtfcatton oft otther residentts att risk:</u> All combustble matteral has been removed ffrom tth@00 hall oxygen sttorage room There is no otther oxygen sttorage room in tthe ftacility</p> <p>- <u>Measures ttto ensure tthis deftcientt practtce does nottt recur</u> All combustble matteral has been removed ffrom tth@00 hall oxygen sttorage room There is no otther oxygen sttorage room in tthe ftacility Maintenance and Housekeeping sttaft will be reeducattted ttto Lffe Saftetty Code K6. Form (Attachmantt D) will be incorporattted into tthe Housekeeping Departmantt daily schedule ttto ensure a minimum distance oft 5ft between liquid oxygen and combustble matteral is mainttained Form (Attachmantt D) will become partt oft Randolph's Quality Assurance Program ensuring tthe LSC requiremantt oft a minimum oft 5t between liquid oxygen and combustble matteral is mainttained</p> <p>- <u>Monittoring oft correcttve acttgn</u> All combustble matteral has been removed ffrom tth@00 hall oxygen sttorage room There is no otther oxygen sttorage room in tthe ftacility</p>		

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 05/13/2011

FORM APPROVED

OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155231		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 04/25/2011	
NAME OF PROVIDER OR SUPPLIER RANDOLPH NURSING HOME				STREET ADDRESS, CITY, STATE, ZIP CODE 701 S OAK STREET WINCHESTER, IN47394			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
					Form (Attachment D) will be incorporated into the Housekeeping Department daily schedule to ensure a minimum distance of 5ft between liquid oxygen and combustible material is maintained. Form (Attachment D) will become part of Randolph's Quality Assurance Program, ensuring the LSC requirement of a minimum 5ft between liquid oxygen and combustible material is maintained.		